


MEMBER	No OF	BARS PER MEMB	DIA	LENGTH	TOTAL NUM- BER	MARK	S C	B E N D I N G				
								A	B	C	D	E/r
FIRST FLOOR SLAB	1	62	Y12	9350	62	A	37	100				
		10	Y12	5650	10	B	37	100				
		22	Y12	4850	22	C	37	100				
		15	Y12	7350	15	D	37	100				
		32	Y12	8000	32	E	37	100				
		80	Y12	4250	80	F	37	100				
		104	Y12	7500	104	G	37	100				
		25	Y12	7050	25	H	37	100				
		94	Y12	9350	94	J	37	100				
		14	Y12	5650	14	K	37	100				
		16	Y12	4850	16	L	37	100				
		12	Y12	7350	12	M	37	100				
		52	Y12	8000	52	N	37	100				
		118	Y12	4250	118	P	37	100				
		118	Y12	7500	118	Q	37	100				
		20	Y12	7050	20	R	37	100				
STOOLS		75	Y12	700	75	SA	83	200	200	100		

--	--	--	--	--	--	--	--	--	--	--	--	--

	8	10	12	16	20	25	32	40	TOT	Date	18-06-2024	
R										Det by	M.MULUMBA	
Y			4905						4905	Ref Dwg		
TOT			4905						4905	Job No	STRUCT-58	
 <div>PROKON Software Consultants (Pty) Ltd http://www.prokon.com</div>										JW14468- FEMALE ABLUTION STANDBY FACILITY		
										TOP&BOTTOM REINFORCEMENT		
										Revision		
										Schedule No		FIRST FLOOR